

LDEQ Inspection Protocol to comply with the term, “thorough inspection”

Revised 5/5/06

An LDEQ accredited asbestos inspector performs an inspection whereby all suspect Asbestos Containing Material (ACM) is sampled and samples are analyzed by an LDEQ accredited laboratory, utilizing Polarized Light Microscopy (PLM):

This includes but is not limited to:

- 1- Friable material such as walls, ceilings, insulating materials, floor coverings, fire proofing, window caulking, etc;
- 2- Category I nonfriable ACM that has become friable;
- 3- Category I nonfriable ACM that will be or has been subjected to sanding, grinding, cutting, or abrading, in accordance with 40 CFR Subpart M-National Emission Standard for Asbestos, 61.141. Definitions; and
- 4- Category II nonfriable ACM that has a high probability of becoming or has become crumbled, pulverized, or reduced to powder by the forces expected to act on the material in the course of demolition or renovation operations.

Category II material such as cement asbestos containing roofing shingles and siding are to be assumed ACM.

The number of samples taken shall be in accordance with the Asbestos Hazard Emergency Response Act (AHERA). Where feasible, AHERA should be employed with the exception of a partial inspection.

An inspector may make a determination that Category I material such as resilient floor covering, caulking, etc. is in good condition by administering hand pressure. If the material is not friable and in good condition, it is not necessary to sample the material because it is Category 1 in good condition that does not have a high probability of becoming regulated ACM, and is therefore considered to be non regulated.

Partial Inspection

Where a “thorough inspection” can be conducted on the majority of the structure, including sampling of suspect ACM if any is present, that procedure will be completed to the extent possible. If suspect RACM is present and verified by sampling to be RACM, the structure will be demolished and disposed as RACM. In the case where the partial inspection reveals either no suspect RACM or sampling demonstrates that no RACM is present, that part of the structure will be demolished as C&D debris.

After the unstable/inaccessible portions of the structure are made safe and accessible, the accredited asbestos inspector will verify that the materials in that part of the structure are homogeneous with the materials that were inspected during the partial inspection. If determined to be homogeneous and no other RACM is identified, the remainder of the structure will be determined to be C&D debris. However, if the inspector determines that the materials in the unstable/inaccessible portion of the structure are not homogeneous or that RACM is present, the unstable/inaccessible portion of the structure will be demolished and disposed as RACM.